EPA		United States Environmental Protection Agency Washington, DC 20460 Work Assignment			Work Assignment Number 4 = 0.2	
LFA	Work				Other Amendment Number.	
Contract Number	Contract Period ()	14/29/2011 to 0	03/31/2015	Title of Work Assign	THERWSF Site Name	
EP-D-11-006	Base	Option Period Number	3	Address MDL		
Contactor EASTERN RESEARCH GROUP	, INC.	Specify Sec	ction and paragraph o	of Contract SOW		
Purpose X Vitirik Assignment Vitirik Assignment X Vitirik Plan Approx	Work Assignment Close-Out		Period of Performance From 04/01/2014 To 03/31/2015			
Comments The work plan dated 04/25/1 estimated cost 955,524 and not exceed costs of 550,000	completion date 03/3 until authorized by	31/15 as specified. y a change in the W	Due to bud A.			
Superfund	٨	occounting and Appropriat	ons Data		X Non-Superfund	
S (Max 6) (Max 4) Co.	propriation Budget Grg/Cod ide (Max 6) (Max 7)		bject Class Amou (Max 4)	urt (Dolans) (Cens)	See/Project Cost Dry/Code (Max 8) (Max 7)	
1						
2						
1						
4						
1						
Contract Period		Authorized Work Assignm				
04/29/2011 to 03/31/20: The Action	CossFee \$0.00 15 555,524.	00	,	378		
Course - 10	err roa	6.6		220		
Total	\$55,524.1		- Conservate	378		
Contractor WP Daned 04/25/201		Work Plan / Cost Estimate \$55,524,00		LOE 378		
Cumulative Approved	Contifee	\$55,524.00		to€ 378		
		222, 224.00		8 18 18 18 18 18 18 18 18 18 18 18 18 18		
Work Assignment Manager Name KE1.5	ten Benedict		-	Branch/Mail Code. Phone Number		
(Express on)	-					
(Sgrature) (Date) Project Officer Name _ Karten C _ Watson + Q				FAX Number		
MARGACET DO	UGHERTY Ad		Phone Number 919-541-3114			
(Sgnature)				FAX Number 919-	241-3114	
Other Agency Official Name	(Date)		Branch/Mail Code			
CTAPA TOTAL TARREST CONTRACTOR		-		Phone Number		
(Sprature)		(Date)		FAX Number		
	Daryl Jones	jamej.		Branch/Mail Code.		
B-low-A	10		Phone Number: 919-541-3112			
(Lagrand 1)	aryl!		12201	7191911911911911 343	341 3111	

EPA	Was	onmental Protection Agency shington, DC 20460 Assignment	Work Assignment Number 4-02 Other Amendment Number.		
Contract Number EP-D-11-006 Contractor	Base	Option Period Number 3 Specify Section and paragraph	Address MDL Iss		
Purpose X Work Assigns Work Assigns Work Plan Ag	ment ment Amendment	I & II Wark Assignment Close-Out Incremental Funding	Period of Performance From 04/01/2014	1 Te D3/31/2015	
Comments This work assignment inc This document is IAM the	OM 7,3,5,1(D)	eparation of the work plan and t	o begin work on the wor		
Superfund		Accounting and Appropriations Data of accounting and appropriations date use EPA For		X Non-Superland	
B DCN BudgetFY (Max 4)	Appropriation Budget OnlyCod Code (Max 5) (Max 7)	de Program Element Object Class Amox (Max 9) (Max 4)		//e/Project Cost Org/Code (Max 8) (Max 7)	
2					
2					
4					
5		Authorized Work Assignment Ceiling			
Contract Period	Cost/Fee		LOE		
04/29/2011 To 03/31/ The Action	2015	10		29 5#	
Total					
Contractor WP Dates	CossFee	Work Plan / Cost Estimate Approvals	LOE		
Curtilative Approved	Costfee		LOE		
Work Assignment Manager Name K			Branch/Mail Code		
NON Assignment wanager Name . D.	risten behedict	-	Phone Number		
(Signature	e)	(Clate)	FAX Number:		
Project Officer Name Karen C.			Branch/Mail Code		
			Phone Number: 919-541-	3114	
(Signature	w)	(Date)	FAX Number		
Other Agency Official Name			Branch/Mail Code		
			Phone Number		
j.Signetun			FAX Number		
0.	Y-Daryl Jones		Branch/Mail Code:		
Godney!	sary!	UNK 5 2 7011	Phone Number: 919-541-3112		

Work Assignment

I. Title: Address MDL Issues

Contractor Name: Eastern Research Group

Contract #: EP-D-11-006

WA#: 4-02

Work Assignment Manager (WAM);

Kristen Benedict
U.S. EPA
Office of Air Quality Planning and Standards
Air Quality Assessment Division
Measurement Technology Group (E141-03)
Research Triangle Park, NC 27711

III. Background:

The Clean Air Act (CAA) establishes a national framework for air quality management in the United States. The 1990 amendments to the CAA, while leaving intact the basic structure of this program, mandated both new Federal programs for controlling air pollution and major philosophical changes in some of the existing programs. Notable new programs were the addition of a technology-based approach for controlling air toxics under Title III, the Title IV requirements for the reduction in acid deposition, and the addition of a federally mandated operating permits program under Title V.

The work to be performed under this work assignment supports the U.S. Environmental Protection Agency (EPA), Office of Air Quality Planning and Standards (OAQPS) developing emissions standards for new source performance standards (NSPS), national emission standards for hazardous air pollutants (NESHAP) for source categories and developing standardized prescriptive procedures to characterize emissions from a wide spectrum of controlled and uncontrolled sources (also known as source characterization) and to develop, evaluate and promote compliance assurance monitoring methods.

As part of the effort under this work assignment, the contactor may evaluate alternative test methods and monitoring procedures, develop and promote the proper and consistent application of stationary source and ambient air emissions test and monitoring methods in the development and enforcement of emissions control programs nationally, and develop, evaluate, and demonstrate new emissions measurement technology.

The goal of the tasks in this work assignment is to limit risks to the public from exposure to 188 hazardous air pollutants (HAPs) and criteria pollutants that are listed in the CAA. The maximum achievable control technology (MACT) standards have been published for almost all source categories. EPA continues to revise MACT standards and to include residual risk standards which are designed to reduce any unacceptable public health risks from major sources.

This work assignment is a continuation of ERG EPD11006 WA 3-02. No work will be duplicated from previous efforts.

IV. Description and Tasks:

Task #1: Work Plan

The Contractor shall initiate and coordinate the technical activities of the staff assigned to this project. The contractor shall prepare a work plan describing the technical approach for each of the tasks in this work assignment. In addition the contractor shall provide a cost and labor estimate for the total work assignment and the cost and labor required to complete each of the work assignment tasks. The contractor shall plan for monthly technical conference calls to brief the WAM and EPA team on progress or issues to complete each task. The Contractor shall provide monthly reports to the EPA contracting officer representative (COR) for this work assignment (WA). Monthly progress reports are required by the contract deliverables and must contain a summary of technical progress and work assignment resource use (labor and cost) information as required by the contract.

Task #2: QAPP Development for Task #3

Under technical direction of the WAM, the Contractor shall prepare draft and final Category III QAPP, which will address all technical and data collection of metals analysis data as outline in Task #3. The QAPP will be prepared in accordance with the format in EPA/240/B-01/003, "EPA Requirements for Quality Assurance Project Plans (EPA QA/R-5)." After review, the Contractor shall address EPA's comments and provide the Final QAPP to EPA for approval.

Task #3: MDL Study

The Contractor shall locate an appropriate set of Method 29 samples for homogenization into a "seed" sample for this project. The set of samples shall be from a well controlled combustion source that contains a variety of metal and other interferents (e.g. excess post digestion samples from a municipal waste combustor compliance test). The contractor shall use this single sample for all spiking and analysis. The contractor shall analyzed the "seed" sample 7 times using ICP and ICP-MS techniques as described in Method 29/6010/6020 for all CAA toxic metals(Sb,Ar,Be,Cd,Cr,Co,Pb,Mn,Ni,Se) except for Hg (14 analysis total). The contractor shall also spike and analyze 7 aliquots of the "seed" sample with nominal levels 1, 3, 10, 50 ng/mL using ICP and ICP-MS(56 analysis total). The contractor shall summarize all results in a tabular form in a letter report. The letter report shall also include example calculations of the spike and spike recovery. The letter report shall include all raw data including cal curves, spike volumes, spike amounts, spike traceability, raw results, etc.

Task #4 QAPP Development for Task #5

Under technical direction of the WAM, the Contractor shall prepare draft and final Category III QAPPs addressing the data collection and technical analysis of carbon monoxide (CO) as outlined in Task #5. The QAPP will be prepared in accordance with the format in EPA/240/B-01/003, "EPA Requirements for Quality Assurance Project Plans (EPA QA/R-5)." After review, the Contractor shall address EPA's comments and provide the Final QAPP to EPA for approval.

Task # 5 Low CO MDL Study

The Contractor shall evaluate low CO monitor performance using two identical CO monitors that meet the requirements of Method 10. The monitors will be set and calibrated to different span values (e.g. 0-10ppm and 0-200ppm) and tested using a matrix sample of CO, CO₂, and nitrogen or air, around a specified CO detection limit (e.g. 8.1ppm). Under technical direction of the WAM, the experiment shall be repeated twice more (e.g. for a 0-200ppm versus 0-1000ppm span around a CO detection limit of 40.5ppm and for a 0-10ppm versus 0-10ppm span around a CO detection limit of 0.76ppm). Each instrument shall be calibrated at the span per Method 10 and should consist of at least 5 points with at least one value below, one value at, and one value above the targeted CO detection limit. A data acquisition system should record and retain data on a 1 to 5 second scale. The contractor shall summarize all results in a tabular form in a letter report. The letter report shall include all raw data (e.g. calibration curves, gas certification of analysis, CO monitor interference check, etc).

Task #6 Collection of Additional Data

Upon technical direction, the Contractor shall gather readily available lab and/or test reports from well controlled combustion sources that contains relevant Method 29 data (e.g. matrix spike amount spiked values, matrix spike duplicate amount spiked values, matrix spike amount found values, matrix spike amount found duplicate values, matrix spike units, volumes, and percent recoveries) and provide the reports to EPA.

V. QA Requirements:

The contractor shall follow the appropriate QAPP for Tasks 3 and 5.

VI. Deliverables:

The Contractor shall adhere to the following schedule for each pollutant:

Task	Deliverable	Delivery Schedule
1	Work Plan	20 days after effective date of WA
2	Draft QAPP	8 weeks after effective date of WA
	Finalized QAPP	2 weeks after receiving comments
3	Letter Report	12 weeks after QAPP approval
4	Revised Work Plan	20 days after effective date of WA Mod*
5	Revised Draft QAPP	8 weeks after effective date of WA Mod*
	Revised Finalized QAPP	2 weeks after receiving comments
6	Revised Letter Report	12 weeks after revised QAPP approval
7.	Matrix Spike Data	3 weeks after revised letter report

^{*}Mod is short for Modification